







## **Display NOM11**

This display is intended as a fast and simple addition into existing measuring systems to show both the original signal and the calculated measurement value. The display works with the usual power supply of the sensor, therefore no additional power source is necessary. Due to the low price, this display can both be used to quickly check on sensors, as well as remain with a sensor indefinately.

The display lighting keeps the output readable even in the dark. Furthermore the display can be rotated a bit around the electrical connection, making it even easier to use.

With its quick configuration, this display becomes a tool to check measurement systems during normal operation.

#### Technical data

Signal	4 – 20 mA (Two-wire) or 0 – 10 VDC (Three-wire)
Display	-1999 – 19999 (4,5 digits LCD) main display, 0 – 100% Signal input display, unit display: Kpa, Mpa, Pa, Bar, mbar, PSI, °C, °F, kg/cm², atm, mmHg, mH2O, m, cm, mm, V, mV, A, mA
Internal resolution	16-bit AD
Accuracy	0,1 %
Voltage drop	< 3,5 V DC
Permissible temperature	Operating temperature: -20°C bis 70°C
Temperature drift	< 50 ppm
Scope of delivery	Display, gasket, long screw (87,5 mm)
Electrical protection	30 mA over current protection, reverse polarity protection
Electrical connection	Usually DIN 43650A, M12 on request
Degree of protection	IP 65
Size	58 mm (Height)(DIN 43650A), 42x42mm

NOM11	-	X	х	
Model				
Signal (1 = 0 – 10	OV; 2 = 4 – 20 mA)			
Electrical connection (1 = DIN 43650A; 2 = M12)				










Stand: 06/2020; Änderung vorbehalten, Right of modification reserved, Sous réserve des modifications









# Manual

### Electrical connection:

Pin 4 – 20 mA (Two-Wire) 0 – 10 V (Three-Wire) VCC(+) VCC(+)1 2 Ground Signal 3 empty Signal

## Configuration:

- 1. Hold S for the password field. Then enter the password "000006" with the arrow keys. Up to change a digit's value, down to change the digit.
- 2. Then you are in the configuration menu with the following sections:

	Menu label	Input	Possible options
	"Unit" - Displayed unit	S to enter	Kpa, Mpa, Pa, bar, mbar, PSI, °C, °F, kg/cm²,
Up, down for selection		Up, down for selection	atm, mmHG, mH2O, m, cm, mm, V, mV, A,
		S to confirm	mA

"Dot" – Decimal dot S to enter Note: Decimal dot is the same everywhere Up, Down to move the

dot

S to confirm

"Zero" - Low limit S to enter Set the low end of the range

> Up, Down to set S to confirm

"Neg" - Sign S to enter Set the sign (positive or negative value) of

> Up, Down to change the low end of the range

S to confirm

Same as "Zero" "Full" – Upper limit Set the upper end of the range

Set the sign of the upper end of the range "Neg" - Sign As above "Bias" - Correction Correct the displayed value. For example to S to enter correct a deviation of +20, -20 has to be Up, Down to set

> S to confirm entered

"Save" - Save S to enter You have to save in the end, otherwise the

> Up, Down for Y/N changes will be discarded

choice S to confirm

"End" - Leave Menu S to leave

Stand: 06/2020; Änderung vorbehalten, Right of modification reserved, Sous réserve des modifications

Bamberg, HRB 6436